

HABS  
ORE  
15-MED,  
1B-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Road Crew Building (Building #2301) HABS No. OR-160-B  
1319 McAndrews Road  
Medford  
Jackson County  
Oregon

Natalie Brown, Photographer

April 1993

- OR-160-B-1 VIEW OF NORTH SIDE AND WEST FRONT OF ROAD CREW BUILDING (BUILDING #2301) SHOWING OFFICE AREA IN NEAR SECTION, FACING SOUTHEAST.
- OR-160-B-2 VIEW OF WEST FRONT AND SOUTH SIDE OF BUILDING #2301, FACING NORTHEAST.
- OR-160-B-3 VIEW OF INTERIOR OF BUILDING #2301, FACING WEST.
- OR-160-B-4 VIEW OF INTERIOR OF BUILDING #2301, FACING EAST.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.